



**NOTE:**

- MAKE TOTAL OF 6 SNAKE COLUMNS IN THE FOLLOWING COMBINATIONS.

- 1) MAKE 4 SNAKE COLUMNS WITH DEPERATE WEDGE FILLER PIECE.
- 2) MAKE 2 SNAKE COLUMNS WITH-CUT FILLER PIECE.

- 2) MAKE 2 SNAKE COLUMNS  
WITH-OUT FILLER PIECE.

\* SEE ART DIRECTOR AND MODEL FOR CHARACTER FINISH AND DETAILING

**GENERAL NOTES**

- SHOW SET DRAWINGS SERVE AS A COORDINATION TOOL DESCRIBING THE FORM AND DESIGN OF THE SHOW. FINAL FINISH AND CHARACTER IS DETERMINED BY THE ART DIRECTOR.
- REFER TO MODEL AND ILLUSTRATIONS FOR GENERAL ART DIRECTION AND INTENT (CHARACTER AND THEMING).
- REFER TO FACILITY DRAWINGS FOR CURRENT STRUCTURAL AND ARCHITECTURAL INFORMATION.

- \* REFER TO MODEL AND ILLUSTRATIONS FOR GENERAL ART DIRECTION AND INTENT (CHARACTER AND THEMING).

- REFER TO FACILITY DRAWINGS FOR CURRENT STRUCTURAL AND ARCHITECTURAL INFORMATION.

[illegible]